

South Dakota Spill Report Form

PRCF #:

Case #: 2024.176

Reported (MM/DD/YY): 12/10/24		Time:		Recorded By: J. McGuire	
A. REPORTER	Reported By: Duwayne Aman				
	Organization Name: Harms Oil			<input checked="" type="checkbox"/> Discharger <input type="checkbox"/> Public <input type="checkbox"/> State <input type="checkbox"/> Local <input type="checkbox"/> Federal	
	Phone:		Email:		
	Address: 337 22nd Avenue, Ste 100				
	City: Brookings		State: SD	Zip: 57006	
B. DISCHARGER (Responsible Party)	Name: Harms Oil				
	Address:				
	City:		State:	Zip:	
	Phone:		Email:		
C. INCIDENT DATE & LOCATION	<input checked="" type="checkbox"/> As Above in A		Spill Date: (MM/DD/YY) 12/10/24		
	Spill Time:				
	Street or Approx. Location: 1800 Elevator Road, CHS Farmer's Alliance				
	Survey Description: 43.720044, -98.050256				
D. MATERIAL	<input checked="" type="checkbox"/> As Above in B		Spill Date: (MM/DD/YY) 12/10/24		
	Street or Approx. Location: 1800 Elevator Road, CHS Farmer's Alliance				
	Survey Description: 43.720044, -98.050256				
	City: Mitchell		County: Davison	State: SD	Zip: 57301
E. SOURCE	Material type (Code/Name):	<input checked="" type="checkbox"/> Hazardous Substance <input type="checkbox"/> Oil <input type="checkbox"/> Material Unknown <input type="checkbox"/> Other	Quantity Spilled	Spilled in Water	Units (Check one)
	Diesel, Red Dye	~500		<input type="checkbox"/> lb. <input type="checkbox"/> bbl. <input checked="" type="checkbox"/> gal. <input type="checkbox"/> oth.	
				<input type="checkbox"/> lb. <input type="checkbox"/> bbl. <input type="checkbox"/> gal. <input type="checkbox"/> oth.	
				<input type="checkbox"/> lb. <input type="checkbox"/> bbl. <input type="checkbox"/> gal. <input type="checkbox"/> oth.	
F. MEDIUM	Source of Spill: <input checked="" type="checkbox"/> AST <input type="checkbox"/> UST <input type="checkbox"/> Railway <input type="checkbox"/> Transport <input type="checkbox"/> Fixed Facility <input type="checkbox"/> Pipeline <input type="checkbox"/> Highway <input type="checkbox"/> Other				
	Description:				
	Regulated Tank Facility: <input checked="" type="checkbox"/> Tank Facility ID #: 0800027				
G. CAUSE	Medium Affected: <input type="checkbox"/> Air <input checked="" type="checkbox"/> Land <input type="checkbox"/> Water <input type="checkbox"/> Groundwater <input type="checkbox"/> Within Facilities Only				
	Waterway Affected: n/a				
H. DAM-AGES	Reported Cause: <input type="checkbox"/> Transportation Accident <input type="checkbox"/> Operational Error <input type="checkbox"/> Dumping <input type="checkbox"/> Equipment Failure <input type="checkbox"/> Natural Phenomenon <input type="checkbox"/> Unknown <input checked="" type="checkbox"/> Other				
	Description: Overfill				
I. ACTIONS	# of Injuries:		# of Fatalities:		
	Response Action Taken: Release contained in concrete secondary containment. CHS employees began pumping up release.				
J. NOTIFIED	Responding Agency: <input checked="" type="checkbox"/> DANR <input type="checkbox"/> Local <input checked="" type="checkbox"/> Discharger <input type="checkbox"/> Federal <input type="checkbox"/> EPA <input checked="" type="checkbox"/> Other				
	Agencies Notified:				
K. COMMENTS	Comments:				
	Harms Oil hired GeoTek Engineering to perform cleanup. GeoTek plans to pump remaining product, apply booms/pads, and remove affect pea rock.				



**DEPARTMENT of AGRICULTURE
and NATURAL RESOURCES**

JOE FOSS BUILDING
523 E CAPITOL AVE
PIERRE SD 57501-3182
danr.sd.gov

Duwayne Aman
Harms Oil
337 22nd Avenue, Ste 100
Brookings, SD 57006

December 11, 2024

Subject: Department of Agriculture and Natural Resources File Number 2024.176,
pertaining to a diesel overfill at CHS Farmers Alliance, AST Facility ID# 0800027,
1800 Elevator Road, Mitchell, South Dakota.

Dear Mr. Aman:

The Department of Agriculture and Natural Resources (DANR) is contacting you regarding the event noted above. A copy of the initial spill report form is enclosed for your review. Based upon the information provided, an estimated 500 gallons of diesel were released within secondary containment due to an overfill of the aboveground storage tank. It is understood that an environmental consultant has been hired to perform the cleanup. In this situation, DANR requires the following:

- Pump up and properly manage the spilled fuel;
- Collect used absorbents and contaminated pea rock and properly dispose at a permitted municipal solid waste landfill;
- Provide this office with a copy of disposal receipts and documentation regarding management of the recovered fuel along with a copy of your consultant's report documenting cleanup actions, by January 22, 2025; and
- By January 11, 2025, complete and return the Written Contamination Incident Follow Up Report form.

Liam Kirk has been assigned as the project manager for this case. He will review the information provided and will contact you if further remedial action is necessary. If you have questions or need additional information, please do not hesitate to contact him at 605.773.3296. Thank you for your cooperation in this matter.

Sincerely,

Trish Kindt
Inspection, Compliance, & Remediation Program
(605) 773-3296

cc Jeff Bathke, Davison County Emergency Manager
Gary Perowitz, CHS Inc.
Jerry Zutz, GeoTek Engineering & Testing Services, Inc.